



The plastic liner maybe get out in the process of assembly, pls resume it after assembly.

